



Sedona Sewer Cleaning & TV Inspection

Fann Environmental was awarded the second of several phases for the cleaning and camera inspection project for the City of Sedona. The City had divided the collection system into five areas. The project consisted of cleaning the collection system pipe and manholes. Then utilizing a robotic camera, Fann Environmental inspected the integrity of the pipe and individual manholes and provided detailed reports to the Public Works Department of the City. Due to the actual quantities found in Phase 2 versus the bid quantity, Fann Environmental was able to complete Phase 3, 4 and 5 under the contracted quantities. This allowed the City to complete the cleaning and inspection of the system two years ahead of schedule.

Owner: City of Sedona

Final Construction Cost: \$192,910

Project Completion Date: Nov 2008

Fann Environmental Key Personnel:

Robert Upton - Project Manager

References:

Pat Livingstone, City of Sedona, 928-204-7122

